



**GEARED-UP AXIAL DRIVEN TOOL, H=70
EXTERNAL COOLANT, RATIO 1:5.8, (23,200 RPM)**

Tool No.	Spindle	A
P144-00177	ER16	121.8

**GEARED-UP AXIAL DRIVEN TOOL, H=70
COOLANT THROUGH*, RATIO 1:5.8, (23,200 RPM)**

Tool No.	Spindle	A
P144-00178	ER11	134

*Coolant Through tools are designed for 1000 psi.
They require 5 Micron Filtration and **CANNOT** be run dry.